MATERIAL SAFETY DATA SHEET

1" Metal Washer with 2" Nall	Product: Carbon & HSLA * Steel	
	1	
Demand Products, Inc.		
055 Nine North Drive		
Alpharetta, Georgia 30004	Phone Number: (800) 746-5659	

NOTE:

THE FOLLOWING ELEMENTAL BREAKDOWN IDENTIFIES ALL POTENTIALLY HAZARDOUS COMPONENTS IN EXCESS OF 1%, OR WHICH MAY PRESENT A POTENTIAL EXPOSURE HAZARD AT LESS THAN 1%. ELEMENTS CONFIRMED OR SUSPECTED OF CAUSING CANCER ARE

LISTED IF PRESENT IN EXCESS OF 0.1%.

CONCENTRATIONS REPRESENT A MAXIMUM FOR ALL THE GRADES WITHIN A CATEGORY OF STEEL PRODUCTS AND MUST NOT BE INTERPRETED AS A SPECIFICATION FOR A PARTICULAR GRADE.

ELEMENT	CATEGORY - CARBON & HSLA *STEEL	PERMISSIBLE EXPOSURE LIMIT (Mg/M²) (AS FUME)	
	(% MAXIMUM)	P.E.L. (OSHA)	T.L.V. (A.C.O.I.H.)
Iron	> 99.00	10	10
Manganese	1.81	5	1
Nickel	0.50	1	1
Chromium	0.80	1	0.5
Соррег	. 0.60	0.1	0.2
Vanadium	0.15	0,1	0.05

COATING DESCRIPTION

Zinc, Chemically passivated with a chromium compound and/or oil.

All galvanized nails

HIGH STRENGTH LOW ALLOY STEEL

HEALTH HA	ZARD DATA
EFFECTS OF OVEREXPOSURE	
INHALATION - ACUTE EFFECTS High concentrations	of furne may cause respiratory irritation.
- CHRONIC EFFECTS Prolonged exposure to fume may cause re	enleston difficulty.
SKIN CONTACT	sprigtory orinizatiy.
Demaritis may result from prolonged or reg	peated contact with coating
SKIN ABSORPTION	
N/A EYE CONTACT	
irritation may result from contact with coating	1g,
INGESTION	
EMERGENCY AND FIRST AID PROCEDURES	
EMERGENCY AND FIRST AID PROCEDURES EYE Flush with plenty of water.	•
SKIN	<u></u>
Wash contaminated area with soap and we	iter.
INHALATION	· · · · · · · · · · · · · · · · · · ·
Move to fresh air if furne exposure causes i	mitation.
INGESTION N/A	
REACTIV	ITY DATA
CONDITIONS CONTRIBUTING TO INSTABILITY	
REACTIVITY	
May react with mineral acids to release hyd	drogen, an explosive gas.
HAZARDOUS DECOMPOSTION PRODUCTS	
N/A	
SPECIAL PROTECT	TION INFORMATION
VENTILATION REQUIREMENTS	
Torch cutting and walding should be perfor	med with adequate ventilation.
RESPIRATORY PROTECTION	sutting or welding in a poorly ventilated area.
EYE PROTECTION	PROTECTIVE GLOVES
Required for grinding, welding, etc.	Recommended if prolonged contact is required.
OTHER CLOTHING AND EQUIPMENT	
SPECIAL PR	RECAUTIONS
PRECAUTIONARY STATEMENTS	
Chromium and nickel have been included	on IARC's list of carcinogens. Effective furne control is necessary
OTHER HANDLING AND STORAGE PRECAUTIONS	
Barrier cream may be utilized when hand	ing chromium treated material. DATE:
PREPARED BY:	
G.L. Majury	November 1985
POSITION:	<u></u>
Industrial Hyglenist	
-	